


**Craft ROBO Pro & Craft ROBO Pro II (CE5000-40 & CE3000-40)
Craft ROBO (CC200 & CC100)**

What is a Registration Mark?

The “L” shape registration mark when selected, appears on 3 to 4 corners of a document. The markings allow the Craft ROBO’s optical eye to read and register the location of graphics and cutting lines. The RMS (registration mark sensor) is one of the special features that makes the Craft ROBO series stand out among other desktop cutting plotters on the market.



Registration Marks must be printed with the graphics/image.